



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D4306-043

Job Sheet 202198



Part No: D4306-043

Job Qty: 4 pcs

Part Name: Rib Assembly, LH



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 10/22/19

Job Tracking No:

Due Date: 11/4/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV C SHEETS 1,3,4 IPP Rev:A 11.01.20 new issue DD verf:EC IPP Rev:B 11.03.03 AS PER DWG
REV.C DD verf:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup	Run	Workcenter / Supplier	Lead Time	
100	Large Fab - Basket - 1	4 pcs	11/4/19		0.00	9.09	Large Fab - 1		
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		MAL
							Large Fab - 7		
							Large Fab - 8		
							Large Fab - 9		
							Large Fab - 11 (Various)		
							Large Fab - 12		JL
110	QC 5	4 pcs	11/4/19		0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		
							QC 5 - 30		
							QC 5 - 40		
							QC 5 - 61		



Container No: S235693



Part: D4306 - 043

Job No: 202198

Serial No/Batch: S235693

Revision:

Inspector:

Exp Date:

Instructions: Various STD's

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 11/28/19

Plex 10/22/19 10:24 AM Dart.lajeunesse.marie

Labour Welding not accounting
on this job - \$

120 QC 10	4 pcs	11/4/19	0.00 0.00	QC 5 - 81	
				QC 10 - 10	
				QC 10 - 18	
				QC 10 - 24	DAS
				QC 10 - 43	24
				QC 10 - 50	9-89
				QC 10 - 58	
				QC 10 - 9	
				QC 10 - 68	
130 Packaging 3-1 - Stock - B4B	4 pcs	11/4/19	0.00 0.00	Packaging 3 - 1 - B4B	
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	
				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	
				Packaging 3 - 6 - B4B	
				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	DAS
				Packaging 3 - 18 - B4B	24
				Packaging 3 - 19 - B4B	9-89
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
140 QC 21 - SA	4 pcs	11/4/19	0.00 0.00	QC 21 - SA - 21	DAS
				QC 21 - SA - 70	21
				QC 21 - SA - 53	3-89

Part Op 100 - Weld per dwg A/R S.S. rod Batch: *MT39015* - 1- Cut tube 52" *** Make line at 10.00" and use jig for other lines, Descriptions: and ensure seam in place on side of tube when bending*** 3- Trim access tube material to finish size and cut notch as per dwg D4306-3 4- Drill and chamfer holes as per dwg D4306-3 using DT9710 5- weld bushing as per dwg D4306

110 - QC5- Inspect part completeness to step on W/O

120 - QC10- Inspect visual per QSI004- ground welds

130 - Identify as per dwg & Stock Location: _____ -LOCATION: WA004-4

140 - QC21- Final Inspection - Work Order Release

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D3759-1	Bushing	16 pcs (4 ea)	100-Large Fab - Basket - 1	14x50x310 2x52x1050
M304TS0.750W.049	304 Sq Tube .75X.75X.049W	16.6640 ft (4.166 ea)	100-Large Fab - Basket - 1	5232146

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Basket - 1	D3759-1	16	235	0
	M304TS0.750W.049	17	337	0

Part Specifications

Specifications could not be found.

Plex 10/22/19 10:24 AM Dart.lajeunesse.marie

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					